Inspection Report

Name of Work	: Pot Hole Filling in Ramachandrapura Area in Ward No. 10, (Doddabommasandra) Vidyarnyapura Sub Division.
Work Order	: EE/BTP/BBMP/E-PMT-07(13885)/WO/181/2015-16 Dated: 19.12.2015
Agency	: H. Gangadhar
B.R. No & Date	: 276 /2015-16 Dated: 29/02/2016.
Bill Amount	: 9,79,800.44
Job Code	: 010-15-000039
P. Code	: P-1771
Date of Inspection	: 07-03-2016

The above said work pot hole filling in Ramachandrapura Area in ward no 10. (Doddabommasandra) Vidyaranyapura Sub Dn, was shown to me by Sri Madhavarao, Concerned A.E.

The above said work was inspected by me along with Concerned A.E. Sri Madhavarao.

The work found to be Satisfactory

Radha
AE W-10

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT